



NOTES:

1. Depth of current transformer compartment shall be 24" minimum.
2. CT compartment shall have hinged door and locking hasp.
3. CT mounting bracket must be adjustable for depth and height.
4. For top feed, reverse diagram configuration.
5. Customer shall furnish detailed drawings for Company approval before equipment is ordered.
6. Check with the Company to determine how many conductors per phase will be used and how many holes will be needed on the termination pad.
7. CT's shall be located approximately 18" below bus.
8. Bus shall be adequately braced to support conductors.
9. Instrument meter socket to be located outside and within 25 feet of CT cabinet. The conduit between shall be min. 1/4 inch.

Revised: 03/10